

Dug hole 10x20x2' deep at point indicated by line & measurements. Found no evidence of corner. Probably destroyed by farming operations. Ran line & chained between Sec corners, at a point on line between Sec. corners at midpoint of same I Reestablished cor. on line with aid established E. lincs N. & E.

2652.0 E. or W. From sec cor.
 1327.0 E. of 1/4 cor stone

Set C.M. over 1-2" tile standing on E. 10
 " C.M. 18" under surface, set line
 Rock to P.C.M.

N. 1/4 cor Sec 15-76-18
 Sd 1-4-25-41
 No. 1551 Kennedy-Butler, Salisbury

