


E 1/2 Cor Sec 17-75-19



Once destroyed by crossroad culvert replacement
 road construction. Replaced using existing, top
 1/2 3' below aspt. Above 2005 3/10/04